

610 Gold SW, Suite 111 Albuquerque, New Mexico, 87102 Phone: 505-843-7643 Fax: 505-246-2232 Web: WaterBank.com

February 9, 2007

Jonathan Trujillo 3 Benta Belen, New Mexico 87002

and

Daniel Trujillo 194 Tafoya Rd Belen, New Mexico 87002

RE:WATER RIGHTS VALIDATION

Dear Mssrs. Trujillo:

Thank you for contacting WaterBank to conduct a Water Rights Validation on the specified properties in Valencia County, New Mexico being designated Middle Rio Grande Conservancy District (MRGCD) Map 85, A2, A3, and A4 Land of Trinidad Romero. A Water Rights Validation offers the client an in-depth analysis of irrigated land and offers a conclusion based on the findings. We must point out that any final determination lies with the Office of the New Mexico State Engineer.

We have researched your Tracts of land in Valencia County at the Office of the State Engineer and have reviewed the following documentation for evidence of irrigation:

- 1917/1918 Rio Grande Drainage Survey
- 1926/1927 MRGCD Plane-Table Drawing Map
- 1927 MRGCD Appraisal Data Sheets
- Aerial Photography from 1935, 1947, 1955, 1963, 1974, 1984, 1996, and 2002

After reviewing this information, please call either William M. Turner or myself at (505) 843-7643 to discuss the findings.

Thank you for choosing WaterBank.

Prepared By:

Reviewed By:

Sally Williams Geologist William M. Turner **Trustee**

Water Right's Validation Checklist

For: Daniel Trujillo and Jon Trujillo MRGCD Map No. 85 Tracts: A2, A3, and A4 Land of Trinidad Romero By: Sally Williams Date: January 31, 2007

1.	Cover Page	<u>X</u>
2.	Synopsis Pages	X
3.	NMOSE – Criteria for Pre-1907 Surface-water Validity	<u>X</u>
4.	MRGCD Property Tax Map Identifying Tracts	<u> X </u>
5.	1917 NMOSE Drainage Survey Overlay	<u> </u>
6.	MRGCD Appraisal Data	<u>X</u>
	Sheet No. <u>6N2E15-107</u> .	
7.	1927 Plane-Table Drawing Map	<u>X</u>
	Map Number. F4-P29 .	
8.	Aerial Photography	<u>X</u>
	Year 1935	<u>X</u>
	1947	<u>X</u>
		_ <u>X</u>
		<u>X</u>
	1974	<u>X</u>
		<u>X</u>
		_ <u>X</u>
		<u>X</u>
9.	Additional Evidence	

Describe:_____

Process for Validation of Pre-1907 Surface-Water Rights

The New Mexico Office of State Engineers Office (NMOSE) uses several criteria to evaluate surface-water rights perfected prior to March 19th, 1907. The first criterion is evidence of irrigation on 1917 Rio Grande Drainage Survey. There are numerous classifications for land identified on this survey including Cultivated Class I and II land, Alkali, Timber, Bosque, Salt Grass, and Sand Dunes. Only lands that fall within Cultivated Class I or II boundaries are recognized by the State Engineer as potentially having pre-1907 water rights. Lands that do not fall under these classifications (Cultivated Class I or II) must show additional Tract specific evidence establishing beneficial use of water on the land prior to 1907. If this first criterion is met, the NMOSE uses the 1926-27 Middle Rio Grande Conservancy District Plane-Table Survey as the second criterion to support continued beneficial use of water. The Plane-Table Survey consists of various map drawings and associated appraisal sheets documenting land use. If these first two criterion have been met the NMOSE uses aerial photography to establish subsequent beneficial use. *See Exhibit A*.

Description of Land

Lot A2 8.48 acres Lot A3 8.48 acres Lot A4 8.481 acres MRGCD Map No. 105 Total= 25.441 acres *See Exhibit B*.

Evaluation: Lot 1

1917 Rio Grande Drainage Survey

Tracts A3 and A4 and the northern 3.17 acres of Tract A2 was classified as Cultivated Class 1 on the 1917 Drainage Survey. This meets the first of the NMOSE's criteria for a valid surface water right. The southern 5.31 acres of the Tract A2 was classified as Alkali. This is a classification that the NMOSE will use to deny the validity of a surface water right, unless additional evidence can be found. *See Exhibit C*.

1927 MRGCD Appraisal Sheets and Plane Table Map Drawing

In 1927 these Tracts were owned by Elias Romero. These Tracts were part of a larger Tract that was 65 acres. The appraisal sheet notes that 54.91 acres were cultivated with alfalfa and grains and 3 acres of orchard and gardens. The rest of the Tract was salt grass. The Plane-Table map shows that part of all of these Tracts were weeds, but the majority of it was cultivated. This Tract Meets the NMOSE second criteria for a valid-pre-1907 surface water right.

See Exhibit D and E.

1935 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1935 aerial photograph. This meets the NMOSE's third criteria for a valid pre-1907 surface-water right. *See Exhibit F.*

1947 Aerial Photograph

These Tracts shows clear evidence of irrigation on the 1947 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit G*

1955 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1955 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit H.*

1963 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1963 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit I.*

1974 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1974 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit J.*

1984 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1984 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit K.*

1996 Aerial Photograph

These Tracts show clear evidence of irrigation on the 1996 aerial photograph. This meets the NMOSE's criteria for continuing cultivation. *See Exhibit L.*

2002 Aerial Photograph

These Tracts show clear evidence of irrigation on the 2002 aerial photograph. It meets the NMOSE's criteria for continuing cultivation. *See Exhibit M.*

Conclusions

On these three Tracts, there are 20.131 acres with valid pre-1907 surface-water rights. This is 42.27 acre feet consumptive use water rights. There are an additional 5.31 acres that possibly have pre-1907 surface water rights if additional evidence can be found that shows they were being cultivated prior 1907. Additional evidence can come from old warranty deeds, census data, and tax records.





Exhibit A


New Mexico Office of State Engineer Criteria for Evaluating Pre-1907 water rights

WaterBank[®]



<u>Exhibit B</u>

2004 Middle Rio Grande Conservancy District Property Tax Map MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



1917-1918 Drainage survey MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit D

1927 Plane-Table Map Drawing F4-P29 Red box outlines the properties

10 MIDDLE RIO GRANDE CONSE	RVANCY DISTRICT		
Serial Number 67721, 15-101			
LAY OF INHERENT CONDITION VALUATION ZON Sale Sale LAY OF INHERENT CONDITION Sale APPRAISERS FAC Sale Sale LAND FERTILITY OF CROP Sale S	ADDRESS TOMP N.M. COUNTY Valencia CITY OR TOWN LOS ROMETO		
Person And Control Carlos And Co	COUNTY V arehara Christian Christian Control PRECINCT 29.		
Present Presen	SCHOOL DIST. 29		
Her	0)A+(21 3.0 0 PO 240.00 000K LOT		
S S S S S S S S S S S S S S S S S S S	SEC SEC		
33445			
E DO X D DE E SE 3 Pasture & Hay	GRANT TO M.C. TRACT		
	SMALL HOLDING CLAIM NO.		
Cardina Site	PUBLIC STATE NO.		
CONSCIENT STATE ST	3) 1/2 1/0 1/0 10 10 50.00 DEED BOOK PAGE		
ET 3 S F S S B Bosque			
Swamp <u>Fred</u> 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			
A MALE STREET STRE			
B A A B B A B A B A B A B A B A B A B A	K. of DULLI'S Poor Le Costanzia Ditchow. E. E.		
Line and the second sec	NUMBER OFFER ON MIL		
A T T S S S S S S S S S S S S S S S S S	SUMMARY OF VALUATION		
Public Series 1	20 1.00 80 80,00 WERE APPRAISERS		
	Present Executed * Erica : Car		
ONE DESTSO	Lands 3736 4573 5522.80		
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1288 1250 123,00		
Signature in the second	Diags. ample. 500/ 500/2 364789		
23 20 20 15 20 15 20 20 20 20 20 20 20 20 20 20 20 20 20	7- Part 16 SWAMPY REVISION		
CLASSIFICATION OF BUILDINGS AND IMPROVEMENTS			
	Approved Volue Amount Tixed Amount Tixed		
	acreage correctient for for for for Purchase for Value of for 2-1-28- G.S. of fee. Easement Damages		
KIND OLE SCHEMARY Mith Present Place Mith Present Place Mith Present Place Mith Plan * Content Place Mith Place M	SKETCHES		
NUND OL Basement OL Outside Stories Stories Outside Stories Mol Of Black Steel Imbersions Steel Steel Import Contents Steel Steel Steel Steel Present Present Present Present Present Present			
10 WITE 1715 C 1200 K 1200 K			
21 AOU 22			
20 COL 200 1 Darwa 7 200 1 5 1 1 1 4 30 200			
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			
3/			
32			
33 12/28/			
35 SUB-TOTAL	★ Value due to execution of Official Plan.		
36 Special	** Renefits due to execution of Official Plan.		
37 Special 1750	successful of situation of the second s		
40 TOTAL	**Benefits due to execution of Official Plan.		

Exhibit E MRGCD Appraisal Sheet 5N1E,36-29 MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero



Exhibit F 1935 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts

Exhibit G 1947 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit H 1955 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit I 1963 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit J 1974 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit K 1984 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit L 1996 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts



Exhibit M 2004 Aerial Photograph MRGCD Map 85, Tracts A2, A3, and A4 Land of Trinidad Romero Red box outlines subject tracts